CASE REPORT - EB-07-PA-401

Run Date: 8/19/2009

		U 2	NOE RELUK		7 121 101			u Date: 0/1//200	
Start 1/10/200	8 Susp. 3/30/	/2008 S	Status: CLOSED	HQ	SolDate:		S	Agent:	
COMPLAINANT					SUBJECT				
Name:		7			, , , , , , , , , , , , , , , , , , ,				
Company:									
Address:									
City:			ST:	2				ST:	
Geo:		2	Zip:				Zip:		
Phone:	C AND STREET		ux:				Aux:		
Email:									
P_Address:									
Notes:				1			***************************************		
				TO THE PERSON NAMED IN COLUMN					
CGeo:	Leave-	Safety	Non-Safety		:SGeo	None		:Special	
Freq:		Complt			:Freq			:Local	
Call: K3CX		i x	YES		:Call			:Master	
Method:PHONE		Confide	YES		· -0:FRN			:ASR	
Entity: Individual - Licensee		Cong.	NO	Individual	- NonLicen :Entity			:Lat,	
To: 097 - Amateur		InfoTrs	NO	999 - Othe				:Long	
		į.			:Utility			:XCityS	
Interference to	o Amateur Con	nmunicat	ions from broadl	and noise i	rom DC to 5 MHz	in/		•	
						-69.23	A STATE OF THE PARTY OF THE PAR	••	
			WORK	EVENTS					
EventDate Ag	gent Event Type	W	eUtility			***************************************			

1/10/2008 COMPLAINT_R Prob. Resolution: On January 10, 2008, Carrie Electric Cable in A that a contact of his is experiencing harmful interference from broadband noise and needs the FCC assistance in identifying the source. Contacted the complainant, who is a licensed amateur. He alleged that he is experiencing harmful interference to his shortwave radio communications at his residence. He said he observes broadband noise from DC to 5 MHz with spikes spaced every 8 kHz. He believes he traced the interference to a house owned by was a second and located at conducted some on/off tests of circuit breakers and electronic devices inside the residence where the suspectred sources was located. The tests had not effect on the interference. The contacted from the interference of First Energy (GPU 610-858-8864. First Energy removed the electric meter from the suspects residence and they said the interference contined. They also by passed the meter with jumpers and First Energy said it had not effect. However, these tests were not done in the presence of the complainant. When the complainant returned home that day the interfernece was gone and was off the air for about 4 days. After that the interferene returned and had not ceased since. The residence where the source is located is about 1/2 miles from the complainant's residence. The interference has been occurring for months. informed the complainant that someone will arrange for an investigation soon.

CASE REPORT - EB-07-PA-401

Run Date: 8/19/2009

1/30/2008

INVESTIGATION invos invinview

Prob. Resolution: On January 30, 2008, conducted an investigation at the subject's residence. along with the complainant was walked around the subject's residence using the FIM-41. The agent observed that the highest field strength reading was emanating from the garage/shop located behing the subject's house. breaker and found that it lead to another panel and opening each of those breakers lead to the receptacles on the rear wall of the garage/shop. After unplugging the equipment one by one the source of interference was determined to be a variable speed control for a drill press. The variable speed control appeared to have been radiating energy back onto the power line and reradiated as RF. The subject and complainant agreed that the drill press will remain unplugged unless it is being used. Below is information for the manufacturer of the variable speed control.

> Ellis Manufacturing Company Inc. 107 W. Railroad Street PO Box 930219 Verona, WI 53593-0219 800-383-5547

1/31/2008

CLOSED

CloseResolveByFCC

Prob. Resolution:

RULE VIOLATIONS



From:

Sent:

Thursday, January 10, 2008 4:24 PM

To:

Subject:

Re: Interference Problem band scope photos

Attachments: 50kcband.JPG; 80mtrband.JPG; 50160bnd.JPG; 160band.JPG

here are the photos. These are off the band scope on my IC-7800 receiver at my house taken around noon. There are 2 shots of each band, one 50Kc either side of 3.8 Mhz and one that shows 3.5 thru 4.0 Mhz. The other 2 are the same except it is from 1.8 to 2 Mhz. As you can see this stuff gets strong and overwhelms all but the strongest ssb signals on the band. This has been going on for months now and anything you could do to help find the source would be greatly appreciated. Thanks again,




RE: Case No. EB-07-PA-401

Please send me the spectrum analyzer pics that you have of the interference.

FCC Philadelphia Office One Oxford Valley Building, Suite 404 2300 East Lincoln Highway

Langhorne, PA 19047



From:	
Sent:	Thursday, January 31, 2008 1:00 PM
To:	
Cc:	
Subjec	t: FW: Noise issue solved!
	uite welcome. All appreciation should go to of our office. Even though has been with us for ear, he is a good engineer and an asset to the FCC.
Dave	
From:	J 1/31/2008 10:06 AM
To:	The first teaching the same of
.,-	A CONTRACT OF THE PARTY OF THE
Cc: Subject:	IKE! Noise Issue solved!
Very inter	esting and this information helps all of us!!
-	
From:	
	dnesday, January 30, 2008 11:55 PM
ito:5	
Subject:	Noise issue solved!
Γο All,	
	day for as the noise that has been destroying my receive on 75/160 Mtr bands has been
found an	d silenced! As many of you know I have been searching for the source for the past 5 months
and had i	parrowed it down to a neighbors house/shop about a mile NE of my QTH but could not identify
what in h	is shop was generating this noise every 8 Kc from the AM broadcast band to above 7 Mhz. All
n my ies t. Everv	AC line was screaming with RF including the service drop from the pole, the electric meter,
ect. Now	what really made this interesting was that the noise was still heard on my portable Yachtboy
receiver v	when I opened the 200 amp main breaker feeding his shop! After exhausting all other resource
i made co	ontact with on the following of the following and explained the whole issue to him. The assigned
i case nu	mber and put me on the list for their next visit to the Reading area. The FCC's Engineer that
strength 1	he site today was
eading I	opened the main breaker and the noise dropped a considerable amount and within 5 to 7
seconds c	iropped to zero! We then opened each breaker and found it lead us to another panel and
opening t	hose breakers lead us to the receptacles on the rear wall of the shop. As we checked and

unplugged each item I saw the last item along the rear wall was a Drill Press with an electronic variable

speed control! Yes this was the source! I unplugged it and the signal strength dropped and slowly went away! I have attached a photo of the speed control.

Now this begs the question why didn't I have the same result when I opened the main breaker while I was listening with my Yachtboy 2 months ago? The only answer I have is that the signal was so strong at that panel my receivers signal strength meter was pinned with the antenna fully collapsed, so when the breaker was opened it took 5-7 seconds for the signal to go away completely. I was concerned about shutting down the whole shop the first time I opened the main breaker so I did a quick off and right back on test. Signal strength meter which was designed for signals "UP TO" 5Mhz was much more sensitive to the change the second the breaker opened, I never saw the change in strength on the Yachtboy. I am assuming the 5-7 seconds for complete shut down was due to a cap in the speed control or motor circuit that had to drain to zero.

When I was researching the possible sources of noise I came across this comment in a review of a HF amp with a step start circuit:

"My second issue deals with the Slow Start circuit. The Slow Start circuit works the way it is intended to work. It utilizes a Motorola TDA1085C standard triac based motor control circuit. In fact, if you look up the TDA1085C application notes, you will essentially see the identical circuit. HOWEVER, unless you have a good LC line filter, which the DX-1d does NOT, you will get triac switching spikes radiated back on your power line which will re-radiate as RF. Unfortunately, I was able to hear this loud and clear on 160m, especially around 1.910 MHz, and no, using the noise blanker on my rig is NOT a solution. To solve the problem, I purchased a commercial line filter from Corcom (at my expense) and installed it in my 240V line. Problem solved:"

Looking up the app notes for the TDA1085C I found it's primary use was for speed control of small HP motors....like the one on the drill press! So that's the story, my neighbor has agreed to only plug the drill press in when he needs to drill a hole and will unplug it when he is finished. Tonight was the first time in 5 months I could tune across 80 and actually hear the weak ones!

I owe a huge "Thank You" to and actually say that a man from the government came to my house today and he really was here to help me!!

4.5

Atrian nd collect us on Coolins highly 1/10/08 - OC upto 500/10 Sportes & ICH spoud
18 W sontain SW
conquire Business - turind 200 mais off did not 90 ALM. Pot jurpes of notes - Bot 1x ws gople
4 ctry 13th few 1x copy Onit pats 11 links

again sejejah